

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**










This diagram illustrates a mechanical assembly in cross-section. The central component is a shaft (15) passing through a housing. A rotor (16) is mounted on the shaft, and a stator (17) surrounds it. A piston (25) is located on the right side, and a spring (23) is on the left. The assembly is shown in a cross-sectional view, with various parts labeled with numbers 1 through 36. A circular arrow labeled 'M' indicates a clockwise rotation around the central axis.






FIG 9